## RTF1 19POL 5 M 094-006680-00000



Foot-operated remote control, current, with connection cable



- Foot-operated remote control, start/stop
- Infinitely adjustable welding current (0% to 100%) depending on the main current preselected at the welding machine.
- Start/stop welding operation
- Operating point setting directly at the site of welding
- For Tetrix, Picotig 200 AC/DC, Pico 180, Pico 220 cel puls, Pico 300 cel / cel PWS and Pico 350 cel puls / cel puls PWS machine series

 Weight
 2.8 kg

 Cable length
 5 m